

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 911 5TH ST		City: OREGON CITY			
USGS Quad Name: Oregon City		GPS	Latitude: 45 21 13 N		Longitude: 122 36 13 W
Township: 02S	Range: 02E	Section: 31	Block: 131	Lot: 4x, 3x	Map #: 22E31AD Tax Lot #: 14500
Date of Construction: c. 1900	Historic Name:			Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling			Associated Archaeological Site: Unknown	
Architectural Classification(s): Front gable and wing		Plan Type/Shape: L-shaped			Number of Stories: 1.5
Foundation Material: Concrete block		Structural Framing: Unknown			Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Vinyl double-hung; vinyl fixed			
Exterior Surface Materials Primary: Channel drop		Secondary:		Decorative:	
Exterior Alterations or Additions/Approximate Date: Full window replacement					
Number and Type of Associated Resources: None					
Integrity: Good	Condition: Good	Local Ranking:			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district					
Not Eligible: <input type="checkbox"/> Intact but lacks distinction					
<input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district					
<input type="checkbox"/> Reversible/Ineligible as it lacks distinction					
<input type="checkbox"/> Irretrievable loss of integrity					
<input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
<p>This 1-1/2 story house sits under a cross gable roof with a wraparound porch on the south and west sides of the house. The porch is covered by a hip roof supported by square columns set on a solid wood balustrade. The porch hip and main gables feature enclosed eaves, and the main gables feature both rake and frieze boards. The house rests on a board formed concrete foundation with a full water table making the transition to the drop siding finished with cornerboards. The windows in the house are all vinyl sash replacements of the original windows, and are primarily 1/1. At the south gable, a 9/9 window with internal muntins is present at the second floor over a large fixed pane with internal muntins at the first floor level. The windows typically feature board trim, and the double-hung windows have projecting hood moldings.</p>					
Statement of Significance:					

Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 911 5TH ST	Local Designation #	SHPO #