

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1103 5TH ST</b>		City: <b>OREGON CITY</b>		
USGS Quad Name: <b>Oregon City</b>		GPS	Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 07 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>159</b>	Lot: <b>5x</b>
Map #: <b>22E31DA</b>	Tax Lot #: <b>700</b>			
Date of Construction: <b>c. 1919</b>	Historic Name:			Historic Use or Function: <b>Domestic - single dwelling</b>
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>			Associated Archaeological Site: <b>Unknown</b>
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>		Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>		Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>		
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary:	Decorative:	
Exterior Alterations or Additions/Approximate Date:		<b>None apparent</b>		
Number and Type of Associated Resources: <b>None</b>				
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:		National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district				
Not Eligible: <input type="checkbox"/> Intact but lacks distinction				
<input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district				
<input type="checkbox"/> Reversible/Ineligible as it lacks distinction				
<input type="checkbox"/> Irretrievable loss of integrity				
<input type="checkbox"/> Not 50 years old				
Description of Physical and Landscape Features:				
<p>This one story house sits under a front gabled roof with a large gabled porch on the south side of the house. The porch gable is supported by round wood columns at the corners and a single tapered square column at the center of the porch. The porch columns rest on a solid wood balustrade that runs across the south and west sides of the porch. The gables feature open eaves with wide barge boards, and the main gable has knee brackets at the corners of the house. The house is entirely clad with double drop siding finished with cornerboards, with the exception of the porch foundation that is clad with wide drop siding. The windows in the house are all 1/1 double-hung wood sash with wide board surrounds on three sides and projecting sills. A brick chimney is centered on the north wall of the house. A basalt retaining wall runs across the south side of the lot.</p>				
Statement of Significance:				
<div style="border: 1px solid black; height: 40px; margin-top: 10px;"></div>				
Researcher/Organization: <b>Alex McMurry / HPNW</b>				Date Recorded: <b>3/25/2002</b>
Survey Form Page 1	Address: <b>1103 5TH ST</b>		Local Designation # <b>SHPO #</b>	