

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>711 11TH ST</b>		City: <b>OREGON CITY</b>			
USGS Quad Name: <b>Oregon City</b>		GPS	Latitude: <b>45 21 31 N</b>		Longitude: <b>122 36 03 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>97</b>	Lot: <b>4x</b>	Map #: <b>22E31AA</b> Tax Lot #: <b>1400</b>
Date of Construction: <b>c. 1910</b>	Historic Name:			Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>			Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Front gable and wing</b>		Plan Type/Shape: <b>Complex</b>			Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>			Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Aluminum sliders; Fixed picture</b>			
Exterior Surface Materials Primary: <b>Asbestos shingle</b>		Secondary: <b>Channel dr</b>	Decorative:		
Exterior Alterations or Additions/Approximate Date: <b>Full siding replacement; Full window replacement</b>					
Number and Type of Associated Resources: <b>One car 1920s garage to east (1)</b>					
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:			National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
					
Description of Physical and Landscape Features:					
This 1-1/2 story front-gable-and-wing house has a complex plan and sits on a poured concrete foundation. The cross gable roof is covered with composition shingles. The house is covered with asbestos shingles. The rear ell is covered with channel drop siding. Windows are primarily fixed picture and aluminum sliders. The west wide window has a hood. Sculpted holly bushes in front yard.					
Statement of Significance:					

Researcher/Organization: <b>Heather Goodson / HPNW</b>			Date Recorded: <b>5/10/2002</b>
Survey Form Page 1	Address: <b>711 11TH ST</b>	Local Designation #	SHPO #