

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 110 CENTER ST		City: OREGON CITY		
USGS Quad Name: Oregon City		GPS	Latitude: 45 21 09 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31	Block: 83	Lot: 6
Date of Construction: c. 1912	Historic Name:			Historic Use or Function: Domestic - single dwelling
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - multiple dwelling			Associated Archaeological Site: Unknown
Architectural Classification(s): Front gable and wing		Plan Type/Shape: Rectangle		Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown		Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum sliders		
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:	
Exterior Alterations or Additions/Approximate Date:		All windows changed to metal, doors, asbestos siding		
Number and Type of Associated Resources: Garage at rear (1)				
Integrity: Fair	Condition: Good	Local Ranking:		National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old				
Description of Physical and Landscape Features: <p>This vernacular house on a poured concrete foundation has a hip roof porch roof. It is a side gable building with a rectangle plan and an additional front facing gable on the south end of the front elevation. There are a pair of 1/1 windows in the gable and two small square windows have been punched in between the porch roof and building roof. Asbestos siding covers the house. The front porch is almost full width and has columns covered in asbestos shingle siding at either side of the entrance steps. A knee wall runs around the front and sides of the porch. Two large metal slider windows and a modern door fill the lower level of the front elevation. It is a multiple family dwelling as it has two mail boxes and two entrance doors. Most if not all of the windows and doors have been changed to new metal versions.</p> <p>There is detached garage in the back.</p>				
Statement of Significance: <p> </p>				
Researcher/Organization: Rebecca Nielsen / HPNW				Date Recorded: 5/17/2002
Survey Form Page 1	Address: 110 CENTER ST		Local Designation #	SHPO #