

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>505 JACKSON ST</b>		City: <b>OREGON CITY</b>		
USGS Quad Name: <b>Oregon City</b>		GPS	Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 04 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>159</b>	Lot: <b>3</b>
Date of Construction: <b>c. 1917</b>		Historic Name:		Historic Use or Function: <b>Domestic - single dwelling</b>
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>		Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>		Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>		
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary:	Decorative:	
Exterior Alterations or Additions/Approximate Date:		<b>Front gable add-on full width of house, with original roof overlapping new.</b>		
Number and Type of Associated Resources: <b>Garage to northeast (1)</b>				
Integrity: <b>Excellent</b>	Condition: <b>Good</b>	Local Ranking:		National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district				
Not Eligible: <input type="checkbox"/> Intact but lacks distinction				
<input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input checked="" type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity				
<input type="checkbox"/> Not 50 years old				
Description of Physical and Landscape Features:				
<p>This front-gabled c.1917 bungalow features exposed rafter tails, knee brackets, flared barge boards, and corner boards. The round edge drop siding ends with a water table and cap. The chimney is stucco. A porch has been added to the rear and features aluminum windows. The gabled entry hood is supported by brackets, the windows are 1/1 wood.</p> <p>There is a two-car non-historic garage to the northeast of the house.</p>				
Statement of Significance:				

Researcher/Organization: <b>Marti Gerdes / HPNW</b>		Date Recorded: <b>5/11/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>505 JACKSON ST</b>	Local Designation #	SHPO #