


# OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>105 JOHN ADAMS ST</b>				City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 07 N</b>	Longitude: <b>122 36 31 W</b>		
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>92</b>	Lot: <b>3</b>	Map #: <b>22E31DB</b> Tax Lot #: <b>6600</b>
Date of Construction: <b>c. 1917</b>		Historic Name:		Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>			Plan Type/Shape: <b>Rectangle</b>		Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete block</b>			Structural Framing: <b>Unknown</b>		Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>			Window Type/Material: <b>1/1 wood double-hung</b>		
Exterior Surface Materials Primary: <b>Vinyl</b>			Secondary:		Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Metal handrail; replacement aluminum picture window</b>					
Number and Type of Associated Resources: <b>None</b>					
Integrity: <b>Good</b>		Condition: <b>Excellent</b>		Local Ranking:	
National Register Listed? <b>No</b>					
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
<p>This c.1917 bungalow style residence is rectangular in plan and has a steeply pitched front facing gable roof with flared ends at the bargeboard supported by simple triangular brackets below the eaves. The inset entry porch encompasses approximately half of the front elevation, which is atypical for the bungalow style. This may indicated a possible alteration of the porch. The porch that remains is supported by large square wood posts, squared balustrade and railing and retains the tongue and groove flooring. The entrance door is possibly original with a 6-pane wood paneled door. Alterations include the possible enclosure of a portion of the front entry porch and metal entry railings. The typical window type is a 1/1 wood double-hung, while a 1/1-aluminum replacement picture window is present on the front elevation. A shed dormer is present at the upper story. Two exposed brick chimneys remain on two elevations.</p>					
Statement of Significance:					

Researcher/Organization: <b>Christy Fockler / HPNW</b>			Date Recorded: <b>4/12/2002</b>		
<b>Survey Form Page 1</b>		Address: <b>105 JOHN ADAMS ST</b>		Local Designation # SHPO #	