

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>509 MONROE ST</b>		City: <b>OREGON CITY</b>			
USGS Quad Name: <b>Oregon City</b>		GPS	Latitude: <b>45 21 13 N</b>		Longitude: <b>122 36 11 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>131</b>	Lot: <b>3x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>14400</b>
Date of Construction: <b>c. 1922</b>	Historic Name:			Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>			Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Square</b>			Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>			Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>4/1 and 1/1 wood double-hung</b>			
Exterior Surface Materials Primary: <b>Plywood</b>		Secondary:		Decorative:	
Exterior Alterations or Additions/Approximate Date:		<b>Exterior siding; porch remodel</b>			
Number and Type of Associated Resources: <b>None</b>					
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:			National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
					
Description of Physical and Landscape Features:					
<p>This c.1922, minimal tract residence had a square shaped plan with a side facing gable roof. A large centered gable roof covers the main concrete entrance porch supported by decorative metal posts on two corners. The windows on the main elevation are 4/1 wood double-hung with fixed aluminum storms attached. Typical on all other elevations, 1/1 wood double-hung window with aluminum storms is present. The exterior siding is horizontal plywood lap. Alterations include a non-historic metal entrance door and a non-historic metal fence surrounding the property.</p>					
Statement of Significance:					

Researcher/Organization: <b>Christy Fockler / HPNW</b>			Date Recorded: <b>4/12/2002</b>
Survey Form Page 1	Address: <b>509 MONROE ST</b>	Local Designation #	SHPO #