


# OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1311 MONROE ST</b>				City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>			GPS Latitude: <b>45 21 34 N</b>		Longitude: <b>122 35 50 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b>	Block: <b>123</b>	Lot: <b>3</b>	Map #: <b>22E32BB</b> Tax Lot #: <b>3800</b>
Date of Construction: <b>c. 1930</b>		Historic Name: <b>Krassig, William, House</b>		Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Craftsman</b>			Plan Type/Shape: <b>Complex</b>		Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete block</b>			Structural Framing: <b>Unknown</b>		Moved? <b>Yes</b>
Roof Type/Material: <b>Gable / Composition shingle</b>			Window Type/Material: <b>1/1 wood double-hung</b>		
Exterior Surface Materials Primary: <b>Wood shingle</b>			Secondary:		Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Attached garage (probably inserted when house was moved)</b>					
Number and Type of Associated Resources: <b>None</b>					
Integrity: <b>Good</b>		Condition: <b>Good</b>		Local Ranking: <b>Designated Historic Site</b>	
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
<p>This 1-1/2 story Craftsman has a complex plan and concrete block foundation. The house is believed to have been moved (corroborated by neighbors) which would account for its skewed setting with the main entrance at the south elevation and the secondary entrance to the street. The decorative bargeboards and brackets, wide eaves and wide decorative rafter tails, rake board and molding and window hoods attest to craftsmanship and lend a chalet-style feel to the building as well. The south elevation main entrance has a porch with gable and brackets. The multi-pane door is flanked by side lights. The porch gable of street-facing east elevation extends to cover a built-in garage that is not original. The t&amp;g decked porch appears to have been cut-off close in at the garage end as the siding at this point does not match. The porch has a knee wall and square posts. Most windows are 1/1 double-hung wood with one east window featuring decorative muntins on its upper sash. A square bay with shed roof extends from the north side. A house appears on this spot on the 1950 Sanborns but not on the 1911 or 1925, probably because it was moved here after it was built.</p>					
Statement of Significance:					
William Krassig, a dentist, owned the property at the time this house was constructed.					

Researcher/Organization: <b>Rebecca Nielsen / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1311 MONROE ST</b>	Local Designation #	SHPO #