


OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|--|--|--|--|
| Street Address: 315 JOHN ADAMS ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 21 13 N | Longitude: 122 36 25 W |
| Township: 02S | Range: 02E | Section: 31 Block: 60 Lot: 2x | Map #: 22E31AC Tax Lot #: 9000 |
| Date of Construction: c. 1933 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - single dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Dutch Colonial Revival | | Plan Type/Shape: Square | Number of Stories: 2.0 |
| Foundation Material: Concrete block | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gambrel / Composition shingle | | Window Type/Material: 1/1 aluminum | |
| Exterior Surface Materials Primary: Vinyl | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Screened in porch; exterior siding; window alterations | | | |
| Number and Type of Associated Resources: None | | | |
| Integrity: Fair Condition: Good | | Local Ranking: | National Register Listed? No |
| Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old | | |  |
| Description of Physical and Landscape Features: | | | |
| This large c.1933 house is square in plan with a front and side facing gambrel roof. A hip roof resides over the wrap around entry porch, which is supported by truncated wood posts at the corners and is enclosed with screens above an enclosed knee wall. The windows are 1/1 non-historic aluminum flanked with applied shutters. In some locations, aluminum-sliding windows are present. Alterations include the addition of a small wood deck and stairs that leads to the north elevation of the porch. Non-historic vinyl siding clads the exterior. | | | |
| Statement of Significance: | | | |

| | | |
|--|-----------------------------------|-----------------------------------|
| Researcher/Organization: Christy Fockler / HPNW | | Date Recorded: 4/12/2002 |
| Survey Form Page 1 | Address: 315 JOHN ADAMS ST | Local Designation # SHPO # |