


## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>514 7TH ST</b>					City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>			GPS Latitude: <b>45 21 23 N</b>		Longitude: <b>122 36 20 W</b>	
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>54</b>	Lot: <b>1x, 2x</b>	Map #: <b>22E31AC</b>	Tax Lot #: <b>300</b>
Date of Construction: <b>c. 1940</b>		Historic Name: <b>Walter Little Building</b>			Historic Use or Function: <b>Commerce - specialty shop</b>	
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Wally's Drums</b>			Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Commercial False Front</b>			Plan Type/Shape: <b>Rectangle</b>		Number of Stories: <b>1.0</b>	
Foundation Material: <b>Concrete</b>			Structural Framing: <b>Unknown</b>		Moved? <b>No</b>	
Roof Type/Material: <b>Flat / Built-up</b>			Window Type/Material: <b>Large fixed pane</b>			
Exterior Surface Materials Primary: <b>Asbestos shingle</b>			Secondary:		Decorative:	
Exterior Alterations or Additions/Approximate Date: <b>Asbestos ceramic shingles over channel drop siding; three attached garages at SE corner</b>						
Number and Type of Associated Resources: <b>None</b>						
Integrity: <b>Fair</b> Condition: <b>Fair</b>			Local Ranking: <b>Designated Historic Site</b>		National Register Listed? <b>No</b>	
<div>Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district</div> <div>Not Eligible: <input type="checkbox"/> Intact but lacks distinction</div> <div><input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district</div> <div><input type="checkbox"/> Reversible/Ineligible as it lacks distinction</div> <div><input type="checkbox"/> Irretrievable loss of integrity</div> <div><input type="checkbox"/> Not 50 years old</div>						
Description of Physical and Landscape Features:						
This one story commercial building has a rectangular plan and sits on a concrete foundation. The flat roof is built-up. The walls are covered with asbestos ceramic shingles over the original channel drop siding. Windows are primarily large fixed-pane. The front façade has a recessed main entrance. A suspended wood flat awning provides cover for the front façade. The building was demolished after a fire in 2007.						
Statement of Significance:						
See 512 7th St for significance. This building was attached to 512 7th St.						

Researcher/Organization: <b>Bernadette Niederer / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>514 7TH ST</b>	Local Designation #	SHPO #